

QUOTATION		
DATE	NUMBER	PAGE
7/25/2022	0047667	1 of 3

B PIT145  
 I  
 L PITTSFIELD CHARTER TOWNSHIP  
 L 4467 CONCOURSE DR.  
 T ANN ARBOR, MI 48108  
 O

Accepted By: \_\_\_\_\_

Company: \_\_\_\_\_

Date: \_\_\_\_\_

PO#: \_\_\_\_\_

ATTENTION:

CHRIS BLOMMER

734-649-6272

blommerc@pittsfield-mi.gov

WE ARE PLEASED TO PROPOSE THE FOLLOWING FOR YOUR CONSIDERATION:

CUSTOMER REF/PO#		JOB TITLE	SLP	SHIPPING TYPE
		COOLING TOWER P3, PROCESS SYSTEMS,PUMP,20Y-6500, COOLING WATER	REA/CRB	FIELD SERVICE
QTY	DESCRIPTION			

THE FOLLOWING QUOTE IS FOR THE COST OF LABOR AND MATERIALS TO REPAIR THE ABOVE REFERENCED PUMP.

**NEW PARTS REQUIRED:**

\*\*\*\*\*

- (2) THRUST BEARINGS
- (1) RADIAL BEARING
- (2) BEARING LOCK WASHERS
- (2) BEARING LOCKNUT
- (2) OIL RINGS
- (1) SET OF FITTINGS
- (2) MECHANICAL SEALS
- (1) CASING GASKET
- (2) BEARING HOUSING GASKETS
- (2) SNAP RINGS
- (1) MOTOR COUPLING
- (1) PUMP COUPLING
- (1) COUPLING INSERT
- (2) OIL HOUSING GASKETS
- (1) SET OF SHIMS
- (2) OILERS
- (2) SIGHT GLASSES

**LABOR REQUIRED:**

\*\*\*\*\*

PICKUP AT JOB SITE AND TRANSPORT TO KENNEDY INDUSTRIES' WIXOM REPAIR FACILITY.

DISASSEMBLE COMPLETE PUMP.

SANDBLAST COMPONENTS AND PREP FOR INSPECTION.

DIMENSIONALLY MEASURE ALL OPERATING CLEARANCES AND RECORD ON INSPECTION REPORT.

PREP MACHINE SHAFT FOR HARD CHROME PLATING AT TE BEARING FIT.

CHROME PLATE JOURNALS THEN GRIND TO O.E.M. SPECIFICATIONS.

CHASE THREADS OF SHAFT FOR TE BEARING NUT.

POLISH IMPELLER RINGS.

QUOTATION		
DATE	NUMBER	PAGE
7/25/2022	0047667	2 of 3

QTY	DESCRIPTION
-----	-------------

EPOXY COAT CASE.

ASSEMBLE ALL ROTATING PARTS ON SHAFT AND PLACE IN BALANCING MACHINE.

VERIFY T.I.R. THEN DYNAMICALLY BALANCE ROTOR TO 4W/N.

ASSEMBLE ROTATING ELEMENT WITH NEW PARTS LISTED.

INSTALL ROTOR IN PUMP CASING THEN ASSEMBLE COVERS WITH GASKETS AND PINS.

TORQUE COVER BOLTS TO PROPER SPECIFICATIONS.

INSTALL BEARING HOUSINGS.

ADJUST BEARING HOUSINGS TO PROVIDE FREE ROTATION AND PROPER THRUST.

PRESSURE TEST TO ENSURE LEAK FREE.

PAINT THEN PRESERVE PUMP FOR FIELD SERVICE INSTALLATION.

TOTAL REPAIR COST: \$10,795.00

DELIVERY: 7 WEEKS (AFTER RECEIPT OF ORDER)

\*\*\*\*\*

THE FOLLOWING QUOTE IS FOR FIELD SERVICE REQUIRED ON YOUR ABOVE REFERENCED PUMP STATION:

FIELD SERVICE LABOR REQUIRED:

\*\*\*\*\*

KENNEDY INDUSTRIES WILL PROVIDE (2) FIELD SERVICE TECHNICIAN(S) ONSITE TO INSTALL YOUR REPAIRED PATTERSON PUMP #3 & #6, ALIGNMENT, START UP, TEST RUN AND VERIFY PROPER OPERATION.

TOTAL FIELD SERVICE COST: \$4,295.00

\*\*\*\*\*

TOTAL REPAIR COST: \$10,795.00

TOTAL FIELD SERVICE COST: \$4,295.00

TOTAL COST: \$15,090.00

DELIVERY: 7 WEEKS (AFTER RECEIPT OF ORDER)

\*\*\*\*\*

QUOTATION		
DATE	NUMBER	PAGE
7/25/2022	0047667	3 of 3

QTY	DESCRIPTION
-----	-------------

PLEASE PROVIDE WRITTEN OR VERBAL AUTHORIZATION SO THAT WE MAY RESPOND TO YOUR REQUIREMENTS. IF YOU HAVE ANY QUESTIONS, COMMENTS, OR ARE IN NEED OF ANY ADDITIONAL INFORMATION PLEASE FEEL FREE TO CONTACT ME AT (248) 684-1200.

SINCERELY,

MIKE HORN  
REPAIR CENTER MANAGER  
MHORN@KENNEDYIND.COM

CRB

This quote is subject to and incorporates by reference Kennedy Industries, Inc.'s ("Kennedy") Terms & Conditions (Rev'd 4/2019) and Customer Warranty available at [www.kennedyind.com](http://www.kennedyind.com) which will be provided by email upon written request. Kennedy reserves the right to change the Terms & Conditions and Customer Warranty for future orders. By accepting this quote and/or issuing a purchase order relative to this quote, buyer expressly agrees to the provisions set forth in the Terms & Conditions and Customer Warranty posted on Kennedy's website.

**QUOTE VALID FOR 30 DAYS. CREDIT CARD PAYMENTS ARE SUBJECT TO AN ADDITIONAL 3% CHARGE NO TAXES OF ANY KIND ARE INCLUDED IN THIS PROPOSAL. PAYMENT TERMS: NET 30**

**TOTAL: \$15,090.00**